

WIRING DIAGRAM




WARNING


To avoid risk of electrical shock, personal injury or death; disconnect power to washer before servicing, unless testing requires power.

Model : WA5471*, WA5451*

SCHEMATIC DIAGRAM



SCHEMATIC DIAGRAM (NFW7200TW)



MasterSamuraiTech.com

Appliantology.org

SCHEMATIC DIAGRAM

